#### Fax Transmission

Cen	RE(	EI\ FAX	/ED CENTER
			(130 f)

MAY 3 1 2005

Date 5 / 31 /05 Time: 3.40	Ο,
Date 5 / 31 /05 Time: 3,40  Attention to: Mr., X Mrs: Joi Jonason (SILE)	_
Send to: Lanna Mai	_
Fax: (703)877-9306 # of pages with cover: 5	-
Document being transmitted: Here is The proper Format	
for The armended claim That you require	
Additional Information: Thank you For your Time and	•
patience IF you have any questions please Feel	•
free To ConTact Ime	-
Sender Elem ( Niguria)	-
Sender: Edgar ChiquiN  Title: Patent Application	

# BEST AVAILABLE COPY





#### United States Patent and Trademark Office

UNITED STATES DEPARTMENT OF COMMERCE
United States Parent and Trademark Office
Address: COMMISSIONER FOR PATENTS
P.O. Box 1450
Alexandris, Vignia 22313-1450
www.usplo.gov

•				
APPLICATION NO.	FILING DATE	FIRST NAMED INVENTOR	ATTORNEY DOCKET NO.	CONFIRMATION NO.
16/623,404	07/21/2003	Edgar Vicente Chiquin		1067
	7590 05/23/2005		EXAM	INER
Bidgar Chiqu			Hansen, James Orville	
800 Polo Club	Dr.		ART UNIT	PAPER NUMBER
Austin, TX	78737		3637	
İ			DATE MAILED: 05/23/200:	s

Please find below and/or attached an Office communication concerning this application or proceeding.



#### UNITED STATES PATENT AND TRADEMARK OFFICE

COMMISSIONER FOR PATENTS
UNITED STATES PATENT AND TRADEMARK OFFICE
P.O. BOX 1450
ALEXANDRIA, VA 22313-1450

Failure to Acceptably Respond to
Notice of Non-Compliant Amendment (37 CFR 1.121)
No New Time Period for Reply is Provided

	No New Time Period for Reply is Provided	
Complian amendmen In order for	fails to provide the corrective action required by the prior Notice of Non- amendment (37 CFR 1.121) mailed on	
correction	for reply continues to run from the mailing date of the prior Notice of Non-Compliant Amendment. The listed below must be timely filed to avoid abandonment of the application. No new time period for reply is provided munication. See the Manual of Patent Examining Procedure (MPEP) § 714.03.	
abandone	d for reply set forth in the prior Notice of Non-Compliant Amendment has expired, this application will become unless applicant: (1) corrects the deficiency, and (2) obtains an extension of time under 37 CFR 1.136(a). In no case of the SIX (6) MONTH statutory period or obtain an extension for more than FIVE (5) MONTHS date for reply set forth in the prior Notice of Non-Compliant Amendment (37 CFR 1.121).	
1 ( (	OWING CHECKED (X) ITEM(S) CAUSE THE AMENDMENT DOCUMENT TO BE NON-COMPLIANT:  Amendments to the specification:  A. Amended paragraph(s) do not include markings.  B. New paragraph(s) should not be underlined.  C. Other	
(	Abstract:  A. Not presented on a separate sheet. 37 CFR 1.72.  B. Other	
	Amendments to the drawings:	
	A. A complete listing of all of the claims is not present.  B. The listing of claims does not include the text of all pending claims (including withdrawn claims)  C. Each claim has not been provided with the proper status identifier, and as such, the individual status of each claim cannot be identified. Note: the status of every claim must be indicated after its claim number by using one of the following 7 status identifiers: (Original), (Currently amended), (Canceled), (Withdrawn), (Previously presented), (New) and (Not entered).  D. The claims of this amendment paper have not been presented in ascending numerical order.  E. Other St. UNESTE DETOLD THE FURTHER PAPILIATION OF OFFICE ACCUMENTS.	1+
For furth	explanation of the amendment format required by 37 CFR 1.121, see MPEP § 714 and the USPTO website at a spio.gov/web/offices/pac/dapp/opla/prevgnotice/officeflyer.pdf	
Supervise	Through the Legal Instruments Examiner (SLIE)  571 · 272 · 6(0)   Telephone No.	
	5/	

1%

Listing of Claims:

Claim I (Currently amended)

[1. An entertainment movie unit inside a restaurant for viewing movies, the entertainment movie unit comprising:]

In combination a booth, portable DVD player and slid able wooden tray

comprising: a slide able and a portable DVD player positioned underneath the

surface of a [table] [or] booth thereof; [a wooden tray means having a surface for

supporting the portable DVD player;]

[means coupling the tray means and the housing for slide-out movement of the wooden tray means through the underneath of the table or booth to a sliding in and out position wherein the portable DVD player is outside the table or booth and accessible for opening and viewing purposes, and to a closed position wherein the wooden tray is located underneath the table or booth for storage,] wherein the portable DVD player is accessible by sliding out the said wooden tray from said underneath surface of a booth for viewing purposes while in an open position, and is stored underneath the said surface of a booth by sliding in the said wooden tray from said underneath surface of a booth wherein the portable DVD player is stored in a closed position; in which slid able wooden tray is permanently fixed underneath surface of a booth by two wooden side supports with a relatively strong wood adhesive means.

Reply TO O.A.
Filed on May 23, 200=

[an anti-theft wire connected to the wooden tray means; the anti-theft wire having one link on the portable DVD player and the other link on the underneath of the table with a strong adhesive, the link on the portable DVD player cooperating with the housing to slide the wooden tray from underneath table or booth when the tray means is in its slide-out position when the portable DVD player is pivoted to a generally vertically orientation; and]

[means for supporting the tray so that the front of the wooden tray is in generally horizontal orientation while the tray is in its slide-in position, the front face of the wooden tray being relative to the lip of the side said surface from the table or booth means, in a vertical position two side supports fixed to the underneath of the said table or booth with a relatively strong wood adhesive means, and providing support for the wooden tray to slide in and out from underneath the said table or booth and remain in a rested position with the portable DVD player is on its surface mostly always connected for power on a multi AC outlet power tap with other portable DVD players inside the restaurant.]

Claims 2-8 (canceled).

Reply To O.A.
Filed on May 23,2005

## This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

### **BEST AVAILABLE IMAGES**

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:	
☐ BLACK BORDERS	
☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES	
☐ FADED TEXT OR DRAWING	
☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING	
☐ SKEWED/SLANTED IMAGES	
☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS	
GRAY SCALE DOCUMENTS	
LINES OR MARKS ON ORIGINAL DOCUMENT	
☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY	
□ OTHER:	

### IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.